



Power plant locations and source of coal burned

- Powder River
- Illinois Basin
- North W. Virginia/Ohio
- South W. Virginia/Ohio
- Eastern Kentucky
- Pennsylvania/Maryland
- Colorado
- Texas lignite
- Alabama bituminous

BNSF
 CN
 CSX
 NS
 UP
 KCS

Not all lines shown



© 2009 Kalmbach Publishing Co., TRAINS: Robert Wegner
 This material may not be reproduced in any form without permission from the publisher.

See June 2002 TRAINS for map of Eastern power plants

Coal field locations

Coal type:

- Bituminous
- Sub-bituminous
- Lignite

North Dakota
 Michigan
 Pennsylvania/Maryland
 Northern W. Va./Ohio
 Southern W. Va./Ohio
 Illinois Basin
 Green River Basin
 Powder River Basin
 Uinta Basin
 Colorado
 Black Mesa
 San Juan/Raton
 Western Region
 Eastern Kentucky
 Alabama/Tennessee lignite
 Gulf Coast lignite